



 **Additional Warranty Information exhausts, headers and silencers**

- Due to heat formation at the exhaust, the paint on black exhausts can dissolve.
- And chrome and blank exhausts can become slightly discolored as a result.
- This happens more often with incorrectly adjusted ignitions and / or too small nozzles.
- We can therefore not give warranty's on the discoloration or the dissolving of paint on the exhausts.